



John Robinson Associates

Utility Survey Specialists & Consultants

CCTV Drainage Condition Surveys. Through our pre-selected suppliers we can provide detailed CCTV survey of drainage systems plus high pressure pre cleaning/jetting to the highest standard.

Position	Code	Description	CD	Pic	Video Ref
00.0	MH	Start node type, manhole			0:00:00
00.0	WL	Water level 20%	4_1		0:00:00
00.6	DES	Settled deposits fine 20%	4_2		0:00:08
01.1	WL	Water level 5%	4_3		0:00:10
02.3	JDM	Joint displaced medium	4_4		0:00:17
09.0	GP	General photograph	4_5		0:01:30
09.4	WL	Water level 10%	4_6		0:01:42
12.2	WL	Water level 5%	4_7		0:02:09
17.7	OJM	Open joint medium	4_8		0:03:06
20.4	WL	Water level 10%	4_9		0:03:42
20.8	DES	Settled deposits fine 5%	4_1		0:03:49
21.6	WL	Water level 5%	4_1		0:03:55
22.9	JDL	Joint displaced large	4_1		0:04:12
24.7	JDM	Joint displaced medium	4_1		0:04:34
26.6	JDM	Joint displaced medium	4_1		0:04:58
29.2	JDM	Joint displaced medium	4_1		0:05:37
29.7	DEE	Attached deposits, encrustation 04-05 5%	4_1		0:05:47
30.2	WL	Water level 5%	4_1		0:05:54

